


Converter part

Input power supply : AC100/200V  $\pm$ 10% 50/60Hz

Output signal : DC4~20mA Load resistance 450 $\Omega$  or less

DC0~10V Load resistance 5K $\Omega$  or more

		TITLE				PL-110N Pressure level indicator converter dimensions		PROJECTION THIRD ANGLE		SCALE /		DWG No.		A	
		REVISION		APPROVED		CHECKED		DRAWN		DATE		 <b>Y. E. I.</b> C O . , L T D .			
M. K		DATE		REVISION		PL#A6001-2				2002. 09. 27					